United States Of America

Department of Transportation - Federal Abiation Administration

Supplemental Type Certificate

Number SA09574SC-D

This Certificate issued to

RAM Aircraft, Limited Partnership 7505 Karl May Drive Waco, TX 76708

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air Regulations.

Original Product Type Certificate Number:

3A25

Make

Cessna

Model:

340; 340A

Description of Type Design Change: Installation of RAM Series VII 335 horsepower engines, increase takeoff weight to 6,390 pounds, and increase landing weight to 6,075 pounds in accordance with RAM Master Drawing No. 2036, Revision B, dated August 25, 1999, or later FAA approved revision. FAA approved Airplane Flight Manual Supplement, AFMS 1095, dated September 21, 1999, or later FAA approved revision is required.

Limitations and Conditions. RAM vortex generator kit must be installed in accordance with STC SA7975SW-D, and electronic fuel flow gauge must be installed in accordance with STC SA5796SW-D. The installer must determine whether this design change is compatible with previously approved modifications. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: June 01, 1999

Date of issuance. February 29, 2000

Date reissued: September 20, 2002; February 20, 2008; September 11, 2008

Date amended:

By direction of the Administrator

ORIGINAL SIGNED BY TERRY BOWDEN

(Signature)

Terry L. Bowden

DAS administrator

DAS-700100-SW

RAM Aircraft LP

Waco, Texas

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.